# Apparatus Licence

Issued by Delegate of the Australian Communications and Media Authority



Licensee details	
Customer ID	1136941
Licensee	Reach Beyond
Trading name	Reach Beyond
Licensee address	PO Box 291, KILSYTH, VIC 3137

Licence details	
Licence service	Broadcasting
Licence subservice	HF Overseas (IBL) Service
Licence number	1139645/1
Date of issue	02/08/2023
Date of effect	02/08/2023
Date of expiry	08/09/2024

#### Licence conditions

Your licence is subject to conditions set out in the *Radiocommunications Act 1992*. Your licence may also be subject to such other licence conditions as determined by the ACMA (in licence condition determinations) from time to time, and is also subject to special conditions as detailed on this licence.

The conditions that are imposed on a licence vary according to the type of licence issued, the service being operated and the section of the *Radiocommunications Act 1992* under which the licence has been issued. For further information about the conditions that apply to your licence, please contact the ACMA (see contact details below).

#### Rights of appeal

A decision by the ACMA to impose further conditions or revoke or vary the conditions of your licence may be reviewable. If you are affected by, and dissatisfied with, such a decision you may apply to the ACMA to have the ACMA reconsider the decision under section 288 of the *Radiocommunications Act 1992*.

An application for reconsideration must state the reasons for the request, and should be sent to the Customer Service Centre, Australian Communications and Media Authority, PO Box 78, Belconnen, ACT, 2616. Applications for review of decisions can be made using the R051 - Application for review of Decision form, available on the ACMA website.

#### **Important**

An application for the ACMA to reconsider a decision to impose or vary licence conditions must be made to the ACMA within 28 days of the day on which you are informed of the decision. An application for reconsideration made after that time may not be accepted.

#### **ACMA** contact details

Customer Service Centre PO Box 78 BELCONNEN ACT 2616

Telephone: 1300 850 115 Email: info@acma.gov.au

ACMA website: www.acma.gov.au

\_\_\_\_\_

Certain information contained in this licence record will be disclosed in the Register of Radiocommunications Licences (RRL), established and maintained pursuant to Part 3.5 of the *Radiocommunications Act 1992*.

# Advisory Notes applying to licence no.: 1139645/1

Conditions applicable to the operation of HF Overseas (IBL) station(s) authorised under this licence can be found in the Radiocommunications Licence Conditions (Apparatus Licence) Determination. Copies of this determination are available from the ACMA and from the ACMA home page (www.acma.gov.au).

### **Technical characteristics**

Below is a summary of the technical characteristics of the licensed service. Further technical details not displayed here may be found on the ACMA website.

#### **Main Station Site**

#### Station 1:

Site details	
Site ID	140752
	HF Broadcasting Antenna Cluster HCJB Site No 2, off Packsaddle Road 9km SW of, KUNUNURRA WA 6743
Co-ordinates (GDA94)	Latitude: -15.812506 Longitude: 128.666928

<u>Transmitter details</u>		
Assigned frequency	12.000 MHz	
Bandwidth	10.0000 kHz	
Freq. assign. ID	0001063428	
Transmitter power	100.00 kW	
EIRP	15,849.00 MW	
Emission designator	9K00A3EGN	
Antenna details		
Antenna ID	1	
Antenna polarization	H - Horizontal linear	
Antenna azimuth		
Antenna height (m)	0	
Antenna type	Unknown antenna type, size or specifications-	

## **Advisory Notes applying to Station 1**

Transmission of an international broadcasting service, under this licence, is not permitted unless there is in force an International Broadcasting licence that authorised the provision of this service.

## Special Conditions applying to Station 1

The use of the frequency specified on this licence is conditional on the successful completion of coordination through the forum of the Asia-Pacific Broadcasting Union and on the condition that harmful interference is not caused to the operation of stations operating in accordance with the High Frequency Broadcasting Schedule published by the International Telecommunication Union.