

# Apparatus Licence

Issued by Delegate of the Australian Communications and Media Authority



## Licensee details

Customer ID	8126387
Licensee	SPORTS ENTERTAINMENT NETWORK PTY LTD
Trading name	Previously named Crocmedia Pty Ltd
Licensee address	Level 5, 111 Coventry St, SOUTHBANK, VIC 3006

## Licence details

Licence service	Broadcasting
Licence subservice	Narrowband Area Service station(s)
Licence number	1130842/2
Date of issue	07/09/2021
Date of effect	07/09/2021
Date of expiry	31/12/2022

## Licence conditions

Your licence is subject to conditions set out in the *Radiocommunications Act 1992*. Your licence may also be subject to such other licence conditions as determined by the ACMA (in licence condition determinations) from time to time, and is also subject to special conditions as detailed on this licence.

The conditions that are imposed on a licence vary according to the type of licence issued, the service being operated and the section of the *Radiocommunications Act 1992* under which the licence has been issued. For further information about the conditions that apply to your licence, please contact the ACMA (see contact details below).

### **Rights of appeal**

A decision by the ACMA to impose further conditions or revoke or vary the conditions of your licence may be reviewable. If you are affected by, and dissatisfied with, such a decision you may apply to the ACMA to have the ACMA reconsider the decision under section 288 of the *Radiocommunications Act 1992*.

An application for reconsideration must state the reasons for the request, and should be sent to the Customer Service Centre, Australian Communications and Media Authority, PO Box 78, Belconnen, ACT, 2616. Applications for review of decisions can be made using the R051 - Application for review of Decision form, available on the ACMA website.

### **Important**

An application for the ACMA to reconsider a decision to impose or vary licence conditions must be made to the ACMA within 28 days of the day on which you are informed of the decision. An application for reconsideration made after that time may not be accepted.

## ACMA contact details

Customer Service Centre  
PO Box 78  
BELCONNEN ACT 2616

Telephone: 1300 850 115  
Email: [info@acma.gov.au](mailto:info@acma.gov.au)

ACMA website: [www.acma.gov.au](http://www.acma.gov.au)

Certain information contained in this licence record will be disclosed in the Register of Radiocommunications Licences (RRL), established and maintained pursuant to Part 3.5 of the *Radiocommunications Act 1992*.

## **Advisory Notes applying to licence no.: 1130842/2**

Conditions applicable to the operation of Narrowband Area Service station(s) authorised under this licence can be found in the Radiocommunications Licence Conditions (Apparatus Licence) Determination and the Radiocommunications Licence Conditions (Broadcasting Licence) Determination. Copies of these determinations are available from the ACMA and from the ACMA home page ([www.acma.gov.au](http://www.acma.gov.au)).

## Technical characteristics

Below is a summary of the technical characteristics of the licensed service. Further technical details not displayed here may be found on the ACMA website.

### Main Station Site

### Station 1:

#### Site details

Site ID	33629
Site address	Marcom Watson Southern Site, ABELS HILL TAS 7250
Co-ordinates (GDA94)	Latitude: -41.452529 Longitude: 147.215415

#### Transmitter details

Assigned frequency	1611.000 KHz
Bandwidth	6.0000 kHz
Freq. assign. ID	0001149358
Transmitter power	400.00 W
EIRP	
Emission designator	6K00A3E

#### Antenna details

Antenna ID	1
Antenna polarization	V - Vertical linear
Antenna azimuth	
Antenna height (m)	0
Antenna type	Unknown antenna type, size or specifications-

### Special Conditions applying to Station 1

Carrier Frequency : 1.611 MHz

Licence No.1225229 operating at 1611 KHz from site 33492 and licence No.1130842 operating at 1611 KHz from site 33629 do not meet the minimum separation distance required for co channel operation. This service is not afforded protection from interference caused by the operation the MF NAS authorised by licence 1225229.