# Apparatus Licence

Issued by Delegate of the Australian Communications and Media Authority



Licensee details			
Customer ID	1147602		
Licensee	Volunteer Marine Rescue NSW		
Trading name	Marine Rescue NSW		
Licensee address	PO Box 579, CRONULLA, NSW 2230		
Licence details			
Licence service	Land Mobile		
Licence subservice	Land Mobile System - > 30MHz		
Licence number	1943335/1		
Callsign	VMR250		
Date of issue	07/06/2023		
Date of effect	07/06/2023		
Date of expiry	17/07/2024		
Licence conditions			

#### Licence conditions

Your licence is subject to conditions set out in the *Radiocommunications Act 1992*. Your licence may also be subject to such other licence conditions as determined by the ACMA (in licence condition determinations) from time to time, and is also subject to special conditions as detailed on this licence.

The conditions that are imposed on a licence vary according to the type of licence issued, the service being operated and the section of the *Radiocommunications Act 1992* under which the licence has been issued. For further information about the conditions that apply to your licence, please contact the ACMA (see contact details below).

#### Rights of appeal

A decision by the ACMA to impose further conditions or revoke or vary the conditions of your licence may be reviewable. If you are affected by, and dissatisfied with, such a decision you may apply to the ACMA to have the ACMA reconsider the decision under section 288 of the *Radiocommunications Act 1992*.

An application for reconsideration must state the reasons for the request, and should be sent to the Customer Service Centre, Australian Communications and Media Authority, PO Box 78, Belconnen, ACT, 2616. Applications for review of decisions can be made using the R051 - Application for review of Decision form, available on the ACMA website.

#### Important

An application for the ACMA to reconsider a decision to impose or vary licence conditions must be made to the ACMA within 28 days of the day on which you are informed of the decision. An application for reconsideration made after that time may not be accepted.

#### ACMA contact details

Customer Service Centre PO Box 78 BELCONNEN ACT 2616

Telephone: 1300 850 115 Email: info@acma.gov.au

ACMA website: www.acma.gov.au

Certain information contained in this licence record will be disclosed in the Register of Radiocommunications Licences (RRL), established and maintained pursuant to Part 3.5 of the *Radiocommunications Act 1992*.

## Advisory Notes applying to licence no.: 1943335/1

Conditions applicable to the operation of Land Mobile System station(s) authorised under this licence can be found in the Radiocommunications Licence Conditions (Apparatus Licence) Determination and the Radiocommunications Licence Conditions (Land Mobile Licence) Determination. Copies of these determinations are available from the ACMA and from the ACMA home page (www.acma.gov.au).

## **Technical characteristics**

Below is a summary of the technical characteristics of the licensed service. Further technical details not displayed here may be found on the ACMA website.

## **Main Station Site**

Station 1:

Site details					
Site ID	8382				
Site address	Coastguard Tower, BALLINA NSW 2478				
Co-ordinates (GDA94)	Latitude: -28.867169	Longitude:	153.591893		
Transmitter details					
Assigned frequency	154.625000 MHz				
Bandwidth	12.5000 kHz				
Freq. assign. ID	0000945695				
Transmitter power	25.00 W				
EIRP	83.00 W				
Emission designator	10K1F3E				
Antenna details					
Antenna ID	70070				
Antenna polarisation	V - Vertical linear	V - Vertical linear			
Antenna azimuth					
Antenna height (m)	0				
Antenna type	Dipole-D				
Receiver details					
Assigned frequency	154.625000 MHz				
Bandwidth	12.5000 kHz				
Freq. assign. ID	0000945698				
Transmitter power	N/A				
EIRP	N/A				
Emission designator	10K1F3E				
Antenna details					
Antenna ID	70070				
Antenna polarisation	V - Vertical linear				
Antenna azimuth					
Antenna height (m)	0				
Antenna type	Dipole-D				

# **Special Conditions applying to Station 1**

An efficient cavity filter must be fitted between the transceiver and the antenna.